

Terwa B.V.
Kamerlingh Onneslaan 1-3
3401 MZ IJsselstein

Revision date : 29-02-2016
Date : 25-02-2016
Element report number : EAM017841-ALC-20R1
Customer reference : -

TEST REPORT


Project : KIWA audit testing
Reference : E. Hermus
Material connector : 25CrMo4
Material inside thread : 42CrMo4
Material reinforcing steel : BST550

RECIEVED TEST SAMPLES

Specimen	
F17841-ALC-20-1 u/t 3	Three ALC couplers, marked: ALC 20 TW

DESCRIPTION TEST SAMPLES

1x Reference reinforcing steel \varnothing 20 mm, Element mark F17841-20-REF
3x ALC-coupler, dimensions L= 260 mm, type ALC 20 TW 43073 593356 with reinforcing steel \varnothing 20 mm, Element mark F17841-ALC-20-1 through F17841-ALC-20-3



A side

B side

DESTRUCTIVE TESTS

Test method: Conform TO NEN 6008/BRL 0504						[Test temperatuur ° C: ambient]				
Specimen no.	Dia- meter [mm]	Cross- section [mm²]	ReH [MPa]	Rm [MPa]	Rm/ReH	Agt [%]	Place of fracture	*6 [mm]	Rm Ratio *7 [%]	Slip [mm]
F17841-REF	20	314	575	671	1.17	12.1	-	-	-	-
F17841-ALC-20-1	20	314	577	662	1.15	7.7	*3	-	98.7	0.04
F17841-ALC-20-2	20	314	585	639	1.09	5.6	*3	-	95.2	0.03
F17841-ALC-20-3	20	314	585	678	1.16	8.9	*3	-	101.0	0.03
Characteristic requirements acc. NEN 6008 for BST550			≥500		≥1.08	≥5.0				
Requirements according BRL-0504								≥25	≥90	≤0.10

CONCLUSIONS/REMARKS

- The coupler is tested in delivered condition.
The connection is torqued up by Terwa
- *1 The reinforcing steel is broken at A side.
 - *2 The reinforcing steel is broken at B side.
 - *3 The reinforcing steel is slipped out the ALC coupler at A side.
 - *4 The reinforcing steel is slipped out the ALC coupler at B side.
 - *5 The coupler thread sheared off.
 - *6 Distance between place of fracture and beginning of the coupler.
 - *7 Tensile strength percentage between the reinforcing steel connection and the reference reinforcing steel.
 - *8 Not determined.
 - *9 The reinforcing steel is broken in the coupler at A side.
 - *10 The reinforcing steel is broken in the coupler at B side.

Element Materials Technology

Authorised: W.H. Moijer



All characteristics of the above object(s) have, as far as possible and relevant, been verified by Element Materials Technology Amsterdam b.v. (Element). Other information was provided by the purchaser. This information was verified as far as possible and has been copied into this report, unchanged. Element does not bear responsibility for the correctness of this submitted information. We hereby certify that the reported test data is correct and that the above object(s) was (were) tested/examined in accordance with purchaser's requirements and/or the above procedure(s) and/or code(s)/specification(s). On occasion a test is subcontracted by Element, the accreditation number of the subcontracted party is reported. Interpretations, opinions, conclusions and advice are partly based on the examination results and partly on information supplied by the purchaser. This report has legal value only when furnished with an authorized signature. If, upon reproduction, only part of this report is copied, Element will not bear any responsibility for content, purport and conclusions of that reproduction.